Lesson 14. Problem identification and rectification of biogas plants

Question Bank - Answers

5. If the slurry in the digester of floating drum model overflows from the top, the possible reasons are blockage in outlet pipe and improper outlet level .